



Concorde Battery Corporation
 2009 San Bernardino Road
 West Covina, CA 91790
 Phone (800) 757-0303 or (626) 813-1234
 Fax (800) 237-4209 or (626) 813-1235
<http://www.concordebattery.com>

An ISO 9001:2015 + AS9100D Certified Company

List of Emergency Batteries Authorized per FAA TSO-C173
Document No. 5-0404
Revision J Dated 11/02/20
 (Contact Concorde or consult website for latest revision)

| Concorde Battery Part Number | Date of FAA Authorization Letter | Instructions for Continued Airworthiness (Component Maintenance Manual) |
|-------------------------------------|---|--|
| RG-121-1 & RG-121-1[] | December 3, 2007 | CMM 5-0167 |
| RG-121-2 & RG-121-2[] | December 3, 2007 | CMM 5-0167 |
| RG-121-3 & RG-121-3[] | December 3, 2007 | CMM 5-0167 |
| RG-121-4 & RG-121-4[] | December 3, 2007 | CMM 5-0167 |
| RG-122-1 & RG-122-1[] | December 3, 2007 | CMM 5-0167 |
| RG-122-2 & RG-122-2[] | December 3, 2007 | CMM 5-0167 |
| RG-122-3 & RG-122-3[] | December 3, 2007 | CMM 5-0167 |
| RG-122-4 & RG-122-4[] | December 3, 2007 | CMM 5-0167 |
| RG-125 & RG-125[] | July 31, 2008 | CMM 5-0167 |
| RG-126 & RG-126[] | July 31, 2008 | CMM 5-0167 |
| RG-128-1 & RG-128-1[] | June 25, 2008 | CMM 5-0167 |
| RG-128-2 & RG-128-2[] | June 25, 2008 | CMM 5-0167 |
| RG-128-3 & RG-128-3[] | June 25, 2008 | CMM 5-0167 |
| RG-129 & RG-129[] | June 25, 2008 | CMM 5-0167 |
| RG-131 & RG-131[] | January 3, 2008 | CMM 5-0167 |
| RG-132 & RG-132[] | June 25, 2008 | CMM 5-0167 |
| RG-145-1 & RG-145-1[] | December 10, 2010 | CMM 5-0171 |
| RG-145-2 & RG-145-2[] | December 10, 2010 | CMM 5-0171 |
| RG-150-1 & RG-150-2 | March 17, 2016 | CMM 5-0169 |
| RG-150-1[-Y] & RG-150-2[-Y] | March 17, 2016 | CMM 5-0427 |
| RG-150-5[-Y] & RG-150-6[-Y] | March 17, 2016 | CMM 5-0427 |
| RG-300 & RG-300[] | June 15, 2012 | CMM 5-0167 |
| RG-400E/13 & RG-400E/13[] | March 6, 2008 | CMM 5-0171 |
| RG-616 & RG-616[] | December 17, 2013 | CMM 5-0169 |
| RG-1835-1 & RG-1835-1[] | February 19, 2009 | CMM 5-0282 |
| RG-1835-2 & RG-1835-2[] | February 19, 2009 | CMM 5-0282 |